## Technical Bibliography of Borehole Shear Test (BST)

prepared by

## Alan J. Lutenegger, P.E., PhD. F. ASCE January, 2021

Abdelsalam, S.S., Suleiman, M.T. and Sritharan, S., 2012. Enhanced Load-Transfer Analysis for Friction Piles Using a Modified Borehole Shear Test. Geotechnical Testing Journal, ASTM, Vol. 35, No. 6, pp. 879-889.

Ashlock, J.C. and Lu, N., 2012. Interpretation of Borehole Shear Strength Tests of Unsaturated Loess by Suction Stress Characteristic Curves. *GeoCongress 2012*, ASCE, pp. 2562-2571.

Asoudeh, A. and Oh, E., 2014. Strength Parameter Selection in Stability Analysis of Residual Soil Nailed Walls. *International Journal of Geomaterials*, Vol. 7, No. 1, pp. 950-954.

Audibert, J., Aggarwal, D. and Gardner, W., 1982. Study to Investigate the Effects of Skin Friction on the Performance of Drilled Shafts in Cohesive Sols. Technical Report GL-82-1, Vols., I, II and III, U.S. Waterways Experiment Station, 359 pp.

Bankhead, N., Simon, A. and Thomas, R.E., 2013. Experiments, Model Development and Bank Stability Simulations to Assess Bank Erosion Rates and Potential Mitigation. *USDA Forest Service Report 60-6408-8-088*, 89 pp.

Bauer, G.E. and Demartinecourt. J.P., 1985. The Application of the Modified Borehole Shear Device to a Sensitive Clay. *Geotechnical Engineering*, Vol. 16, pp. 167-189.

Bauer, G.E., Selvadurai, A.P. and Demrtinecourt, J.P., 1980. Measurement of the In Situ Strength Properties of Champlain Sea Clay with the Modified Borehole Shear Test Device. Proceedings of the 33<sup>rd</sup> Canadian Geotechnical Conference,.

Bechai, M., Law, K.T., Cragg, C.B.H. and Konard, J.M., 1986. In Situ Testing of Marine Clay for Towerline Foundations. Proceedings of the 39th Canadian Geotechnical Conference, pp. 115-119.

Borg, J., Dewoolkar, M.M. and Bierman, 2014. Assessment of Streambank Stability. *GeoCongress 2014,* ASCE.

Brooks, A., Spencer, J., Olley, J., Pietsch, T., Borombovits, D., Curwen, G., Shellberg, J., Howley, C., Gleeson, A., Simon, A., Bankhead, N., Klimetz, D., Eslami-Endergoli, L. and Bourgeault, A., 2013. Empirically-Based Sediment Budget for the Normanby Basin. Appendix 09: Validity and Calibration of BSTEM for Select Sites on the East Normanby River, QLD, Australia. *Final Report Australian Government's Caring for Our Country, Australian Rivers Institute, Griffith University*. Casagli, N., Rinaldi, M., Gargini, A. and Curini, A., 1999. Pore Water Pressure and Streambank Stability: Results from a Monitoring Site on the Sieve River, Italy. Earth Surface Processes and Landforms, Vol. 24, pp. 1095-1114.

Chang, M.F. and Zhu, H., 2004. Construction Effect on Load Transfer Along Bored Piles. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, Vol. 130, No. 4, pp. 426-437.

Cribb, M. and Darby, S., 2002. Modelling the Influence of Riparian Vegetation on River Bank Erosion. *Environmental Science*.

Dapporto, A., Rinaldi, M., Casgli, N. and Vannocci, P., 2003. Mechanisms of Riverbank Failure Along the Arno River, Central Italy. *Earth Surface Processes and Landforms*, Vol. 28, pp. 1303-1323.

Dapporto, S., Aleotti, P., Casagli, N. and Polloni, G., 2005. Analysis of Shallow Failures Triggered by the 14-16 November 2002 Event in the Albaredo Valley, Valtellina (Northern Italy). *Advances in Geosciences*, Vol. 2, pp. 305-308.

Darby, S.E. and Delbbono, I., 2002. A Model of Equilibrium Bed Topography for Meander Bends with Erodible Banks. *Earth Surface Processes and Landforms*, Vol. 27, pp. 1057-1085.

Darby, S.E., Gessler, D. and Thorne, C.R., 2000. Computer Program for Stability Analysis of Steep Cohesive Riverbanks. *Earth Surface Processes*. Vol. 25, pp. 175-190.

Demartinecourt, J.P. and Bauer, G.E., 1983. The Modified Borehole Shear Device. *Geotechnical Testing Journal*, ASTM, Vol. 6, No. 1, pp. 24-29.

Demartinecourt, J.P., Bauer, G.E. and Soulie, M., F.E., 1985. Analysis of Field Consolidation Curves Obtained with the Modified Borehole Shear Device (BHSD). *International Journal for Numerical and Analytical Methods in Geomechanics*, Vol. 9, pp. 29-47.

Donchev, P. and Lutenegger, A.J., 1984. In Situ Shear Strength of North-Bulgaria Loess by Borehole Shear Test. *Proceedings of the 6th Budapest Conference on Soil Mechanics and Foundation Engineering*, pp.45-50.

Downs, P.W. and Simon, A., 2001. Fluvial Geomorphological Analysis of the Recruitment of Large Woody Debris in the Yalobusha River Network, Central Mississippi, USA. *Geomorphology*, Vol. 37, pp. 65-91.

Easton, C.N., Lohnes, R.A. and Handy, R.L., 1972. In Place c-Φ Shear Strength Test for Subaqueous Sediments. *Proceedings of the International Symposium on the Engineering Properties of Sea-floor Soils and Their Geophysical Identification*, UNESCO, pp. 26-36. Farouz, E., Karnik, B. and Stanley, R., 2005. Use of In situ Testing to Optimize Slope Design in Highly Weathered Shale. *Proceedings of the 2005 Mid-Continent Transportation Research Symposium*.

Farouz, E., Karnik, B. and Stanley, R., 2007. Case Study: Optimization and Monitoring of Slope Design in Highly Weathered Shale. *Proceedings of the 7<sup>th</sup> International Symposium on Field Measurements in Geomechanics*, pp. 1-12.

Fox, N.S. and Handy, R.L., 1966. Shear Test Device for Bore-Holes. *Proceedings of the 2nd International Conference on the International Society for Terrain Vehicle System*.

Fox, N.S., Lohnes, R.A. and Handy, R.L., 1966. Depth Studies of Wisconsin Loess in Southwestern Iowa: IV, Shear Strength. *Proceedings of the Iowa Academy of Sciences*, Vol. 73, pp. 198-204.

Hackney, C.R., Darby, S.E., Parsons, D.R., Leyland, J., Best, J.L., Aalto, R., Nicholas, A.P. and Houseago, R.C., 2020. River Bank Instability from Unsustainable Sand Mining in the Lower Mekong River. Nature Sustainability, Vol. 3, pp. 217-225.

Han, G., Meng, B., Jing, H. and Wu, J., 2019. Field Experimental Study on the Broken Rock Zone of Surrounding Rock and Rock Borehole Shear Tests of the Large Deformation Tunnel. *Advances in Materials Science and Engineering*, 9 pp.

Handy, R.L., 1975. Discussion: Measurement of In-situ Shear Strength. *Proceedings of the Conference on In-Situ Measurement of Soil Properties*, ASCE, Vol. 2, pp. 143-149.

Handy, R.L., 1986. Borehole Shear Test and Slope Stability. *Use of In Situ Tests in Geotechnical Engineering*, ASCE, pp. 161-175.

Handy, R.L. and Ferguson, E.G., 1976. Discussion: Borehole Shear Device. *Proceedings of the Conference on In-Situ Measurement of Soil Properties*, ASCE, Vol. 2, pp. 168-171.

Handy, R.L. and Fox, N.S., 1967. A Soil Borehole Direct Shear Test Device. *Highway Research News,* No. 27, pp. 42-51.

Handy, R.L. and Williams, W.W., 1967. Chemical Stabilization of an Active Landslide. Civil Engineering Magazine, ASCE, Vol. 37, No. 8, pp. 62-65.

Handy, R.L. Schmertmann, J.H., and Lutenegger, A.J., 1985. Borehole Shear Tests in a Shallow Marine Environment. ASTM STP No. 883, pp. 140-153.

Handy, R.L and White, D.J., 2006. Stress Zones Near Displacement Piers: I. Plastic and Liquefied Behavior. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, Vol. 132, No. 1, pp. 54-62.

Higgins, J.D., Fragaszy, R. and Martin, T., 1987. Engineering Design in Loess Soils of Southeastern Washington. *Washington State Department of Transportation Report WA-RD 145.1*, 135 pp.

Irigoyen, A. and Coduto, D., 2015. Shear Strength of Unsaturated Soils Using the Borehole Shear Test. *Proceedings of the 16<sup>th</sup> European Conference on Soil Mechanics and Geotechnical Engineering*, pp. 2933-2938.

Irigoyen, A., Coduto, D., Winter, M.G., Smith, D.M., Eldred, P.J. and Toll, D.G., 2015. Shear Strength of Unsaturated Soils Using the Borehole Shear Test. *Proceedings of the Conference on Geotechnical Engineering for Infrastructure and Development*.

Jeong, S., Lee, K., Kim, J. and Kim, Y., 2017. Analysis of Rainfall-Induced Landslide on Unsaturated Slopes. *Sustainability*, Vol. 9, 20 pp.

Kelley, S.P. and Lutenegger, A.J., 2004. Comparison of In Situ Tests to Determine Properties of a Deltaic Sand. *Proceedings of the 2<sup>nd</sup> International Symposium on Geotechnical Site Characterization,* Porto, Portugal, Vol. 2, pp. 1662-1671.

Khoury, C.N. and Miller, G.A., 2006. Influence of Flooding on Borehole Shear Test (BST) Results in Unsaturated Soil. *Proceedings of the 4th International Conference on Unsaturated Soils*, GSP No. 147, ASCE, 235-246.

Klavon, K., Fox, G., Guertault, L., Lngendoen, E., Enlow, H., Miller, R. and Khanal, A., 2017. Evaluating a Process-Based Model for Use in Streambank Stabilization: Insights on the Bank Stability and Toe Erosion Model (BSTEM). *Earth Surface Processes and Landforms*, Vol. 42, pp. 191-213. (

Kong, L., Li, J., Guo, A. and Zhou, Z., 2017. Influence of Loading Mode and Flooding on In Situ Strength of Expansive Soils by Borehole Shear Tests. *Proceedings of the 19<sup>th</sup> International Conference on Soil Mechanics and Geotechnical Engineering*, pp. 1197-1200.

Lambrechts, J.R. and Rixner, J.J., 1981. Comparison of Shear Strength Values Derived from Laboratory Triaxial, Borehole Shear and Cone Penetration Tests. *ASTM STP 740*, pp. 551-565.

Langendoen, E. and Simon, A., 2008. Modeling the Evolution of Incised Streams. II: Streambank Erosion. *Journal of Hydraulic Engineering*, ASCE, Vol. 905-915.

Langendoen, E.J. and Ursic, M.E., 2014. Bank Erosion and Stabilization of the Big Sioux River Between Dell Rapids and Sioux Falls, S.D. *USDA-ARS National Sedimentation Laboratory Report*, 120 pp.

Langendoen, E., Simon, A., Limetz, L., Bankhead, N. and Ursic, M.E., 2012. Quantifying Sediment Loadings from Streambank Erosion in Selected Agricultural Watersheds Draining to Lake Champlain. *Technical Report No. 72, USDA-ARS National Sedimentation Laboratory*.

Li, J., Kong, L. and Ling, X., 2019. In-Situ Strength Characteristics o=and Stress History Effect of Silty Soil on High-Speed Railway Cut Slope. *Journal of Hunan University of Natural Sciences*, Vol. 46, No. 3, pp. 99-105.

Little, W.C., Thorne, C.R., and Murphy, J.B., 1982. Mass Bank Failure Analysis of Selected Basin Streams. Transactions of the American Society of Agricultural Engineers, Vol. 25, No. 5, pp. 1321-1328.

Lohnes, R.A. and Handy, R.L., 1968a. Slope Angles in Friable Loess. *Journal of Geology*, Vol. 76, pp. 247-258.

Lohnes, R.A. and Handy, R.L., 1968b. Shear Strength of Some Hawaiian Latosols. *Proceedings of the 6th Annual Engineering Geology and Soils Engineering Symposium*, pp. 64-79.

Lohnes, R.A., Millan, A., Demirel, T. and Handy, R.L., 1972a. Tests for Soil Creep. *Highway Research Record* No. 405, pp. 24-33.

Lohnes, R.A., Millan, A. and Handy, R.L., 1972b. In-Situ Measurement of Soil Creep. *Journal of the Soil Mechanics and Foundation Engineering Division*, ASCE, Vol.98, SM1, pp. 143-147.

Lotsari, E., Hackney, C., Salmela, J., Kemp, J., Alho, P. and Darby, S.E., 2020. Sub-Arctic River Bank Dynamics and Driving Process During the Open-Channel Flow Period. Earth Surface Processes and Landforms, Vol. 45, pp. 1198-1216.

Lovern, S.B., Fox, G.A. and Miller, R.B., 2013. Quantifying the Erodibility and Geotechnical Strength of Cohesive Alluvial Soils Following Streambank Reconstruction. *World Environmental and Water Resources Congress*, pp. 2000-2008.

Lutenegger, A.J., Remmes, B.D., and Handy, R.L., 1978. Borehole Shear Tests for Stiff Soils. *Journal of the Geotechnical Engineering Division*, ASCE, Vol. 104, pp. 1403-1407.

Lutenegger, A.J. and Hallberg, G.R., 1981. Borehole Shear Test in Geotechnical Investigations. ASTM STP 740, pp. 566-578.

Lutenegger, A.J., 1983. Discussion of The Modified Borehole Shear Test. *Geotechnical Testing Journal*, ASTM, Vol. 6, No. 3, p. 161.

Lutenegger, A.J., Donchev, P., and Evlogiev, J., 1984. Determination of the Shear Strength of Loess Soils in a Borehole. *Stroitelstvo (Bulgarian)*, Vol. 31, No. 10, pp. 23-26.

Lutenegger, A.J. and Tierney, K., 1986. Pore Pressure Effects in Borehole Shear Testing. *Use of In Situ Tests in Geotechnical Engineering*, ASCE, pp.752-764.

Lutenegger, A.J., 1987. Shear Strength of Prestressed Cohesive Soils. *Journal of Geotechnical Engineering*, ASCE, Vol. 113, pp. 163-168.

Lutenegger, A.J. and Timian, D., 1987. Reproducibility of Borehole Shear Test Results in Marine Clays. *Geotechnical Testing Journal*, ASTM, Vol. 10, pp. 13-18.

Lutenegger, A.J., 1987. Recommended Method for Performing the Borehole Shear Test, *Geotechnical Testing Journal*, ASTM, Vol. 10, pp. 19-25.

Lutenegger, A.J., 1987. In Situ Shear Strength of Friable Loess, *CATENA Supplement No.* 9, pp. 27-34.

Lutenegger, A.J., Smith, B.L., and Kabir, M.G., 1988. Use of In Situ Tests to Predict Uplift Performance of Multihelix Anchors, *Special Topics in Shallow Foundations*, ASCE, pp. 93-109.

Lutenegger, A.J. and Miller, G.A., 1994. Uplift Capacity of Small Diameter Drilled Shafts in Stiff Clay. *Journal of Geotechnical Engineering*, ASCE, Vol. 120, No. 8, pp. 1362-1380.

Lutenegger, A. J. and Adams, M.T., 1999. Tension Tests on Bored Piles in Residual Soil. *Behavioral Characteristics of Residual Soils*, ASCE, pp.43-53.

Lutenegger, A.J. and Mitchell, M.T., 2000. Pullout Tests on Inclined Grouted Anchors in the Clay Crust at the University of Massachusetts National Geotechnical Experimentation Site. *National Geotechnical Experimentation Sites*, ASCE, pp. 321-335

Lutenegger, A.J. and Powell, J.J.M., 2008. Borehole Shear Tests in Stiff London and Gault Clay, *Proceedings of the 3<sup>rd</sup> International Symposium on Site Characterization*, pp. 714-723.

Mayne, P.W., Brown, D., Vinson, J., Schneider, J. and Finke, K., 2000. Site Characterization of Piedmont Residual Soils at the NGES, Opelika, Alabama. *National Geotechnical Experimentation Sites (NGES)*, ASCE, pp. 160-185.

Midgley, T.L., Fox, G.A., Wilson, G.V., Heeren, D.M., Simon, A. and Langendoen, E.J., 2011. Streambank Erosion and Instability Induced by Groundwater Seepage. *ASABE Annual International Meeting*, Louisville, Ky., Paper No. 1110988.

Miller, G.A. and Lutenegger, A.J., 1997. Influence of Pile Plugging on Skin Friction in Overconsolidated Clay. *Journal of Geotechnical Engineering*, ASCE, Vol.123, No. 6, pp. 525-533.

Miller, G.A. and Khoury, C.N., 2012. Observations from Borehole Shear Testing in Unsaturated Soil. *Unsaturated Soils: Research and Applications*, Vol. 1, pp. 113-119.

Miller, G.A., Azad, S., and Hassell, C.E., 1998. Iowa Borehole Shear Testing in Unsaturated Soils. *Proceedings of the 2nd International Conference on Site Characterization*, Vol. 1, pp. 1321-1326.

Murphy, K. and McCartney, J., 2014. Thermal Borehole Shear Device. *Geotechnical Testing Journal*, ASTM, Vol. 37, No. 6, pp.1040-1055.

Nickel, S.H., 1976. Discussion: Borehole Shear Device, *Proceedings of the Conference on In Situ Measurement of Soil Properties*, ASCE, Vol. 2, pp. 172-174.

Ogunro, V., Anderson, B., Starnes, J. and Burrage, R., 2008. Characterization and Geotechnical Properties of Piedmont Residual Soils. *GeoCongress 2008*, ASCE, pp. 44-51.

Parker, C., Simon, A. and Thorne, C., 2008. The Effects of Variability in Bank Material Properties on Riverbank Stability. *Geomorphology*, Vol. 101, No. 4, pp. 533-543.

Pollen-Bankhead, N., Simon, A., Jaeger, K. and Wohl, E., 2009. Destabilization of Streambanks by Removal of Invasive Species in Canyon de Chelly National Monument, Arizona. *Geomorphology*, Vol. 103, pp. 363-374.

Rinaldi, M. and Casagli, N., 1999. Stability of Streambanks Formed in Partially Saturated Soils and Effects of Negative Pore Water Pressures: the Sieve River (Italy). *Geomorphology*, Vol. 26, pp. 253-277.

Rinaldi, M., Casagli, N., Dapporto, S. and Gargini, A., 2004. Monitoring and Modeling of Pore Water Pressure Changes and Riverbank Stability During Flow Events. *Earth Surface Processes and Landforms*, Vol. 29, pp. 237-254.

Ruenkrairergsa, T. and Pimsarn, T., 1982. Deep Hole Lime Stabilization for Unstable Clay Shale Embankment. *Proceedings of the 7<sup>th</sup> Southeast Asian Geotechnical Conference*, pp. 631-645.

Sakamoto, M.Y., Guesser, L.H., Contessi, R.J., Higashi, R.A., Muller, V.S. and Sbrolglia, R.M., 2018. Use of the Borehole Shear Test Method for Geotechnical Mapping of Landslide Risk Areas. *Landslides and Engineered Slopes: Experience, Theory and Practice. Proceedings of the International Symposium on Landslides*, Naples, Italy, 9 pp.

Sbroglia, R.M., Higashi, R.A., Espindola, M.S., Muller, V.S. and Betiatto, 2018. Use of Borehole Shear Test to Obtain Shear Strength Data Comparison with Direct Shear Tests. *Proceedings of the Annual IAEG/AEG Meeting*, Vol. 6, pp. 145-151.

Schmertmann, J.H., 1975. Measurement of In Situ Shear Strength. *Proceedings of the Conference on In Situ Measurement of Soil Properties*, ASCE, Vol. 2, pp. 57-138.

Shields, F.D., Simon, A. and Dabney, S., 2009. Streambank Dewatering for Increased Stability. *Hydrological Processes*, Vol. 23, pp. 1537-1547.

Simon, A. and Collison, J.C., 2002. Quantifying the Mechanical and Hydrologic Effects of Piparian Vegitation on Streambank Stability. *Earth Surface Processes and Landforms*, Vol. 27, pp. 527-546.

Simon, A. and Hupp, C.R., 1991. Geomorphic and Vegetative Recovery Processes Along Modified Stream Channels of West Tennessee. U.S. Geological Survey Open File Report No. 91-502, 154 pp.

Simon, A. and Darby, S.E., 2002. Effectiveness of Grade-Control Structures in Reducing Erosion Along Incised River Channels: the Case of Hotophia Creek, Mississippi. Geomorphology, Vol. 42, pp. 229-254.

Simon, A. and Thomas, R.E., 2002. Processes and Forms of an Unstable Alluvial System with Resistant Cohesive Streambeds. *Earth Surface Processes and Landforms*, Vol. 27, pp. 699-178.

Simon, A., Larsen, M.C. and Hupp, C.R., 1990. The Role of Soil Processes in Determining Mechanisms of Slope Failure and Hillslope Developments in a Humid-Tropical Forest Eastern Puerto Rico. *Geomorphology*, Vol. 3, Issues 3-4, pp. 263-286.

Simon, A., Curini, A., Darby, S.E. and Langendoen, E.j., 2000. Bank and Near-Bank Processes in an Incised Channel. Geomorphology, Vol. 35, pp. 193-217.

Simon, A., Thomas, R.E., Collison, A. and Dickerson, W., 2002. Erodibility of Cohesive Streambeds in the Yalobusha River System. *USDA National Sedimentation Laboratory Research Report No.* 26, 121 pp.

Simon, A., Thomas, R. E., Curini, A. and Shields, Jr., F. D., 2002. Case Study: Channel Stability of the Missouri River, Eastern Montana. *Journal of Hydraulic Engineering,* ASCE, Vol. 128, No. 10, pp. 880-890.

Singh, A. and Bhargava, S.N., 1979. Shear Test in a Bore Hole. Proceedings of the International Symposium on In Situ Testing of Soil and Rocks and Performance of Structures, Roorkee, pp. 417-421.

Soenksen, P.J., Turner, M.J., Dietsch, B.J., and Simon, A., 2003. Stream Bank Stability in Eastern Nebraska. *US Department of the Interior, USGS, Water-Resources Investigations Report* 03-4265, 102 pp.

Suleiman, M.T. and Xiao, S., 2014. Soil-Pile Interaction of Geothermal eep Foundations. Proceedings of the 27<sup>th</sup> Central Pennsylvania Geotechnical Conference, pp. 1-22.

Sulieman, M.T., Abdelsalam, S. and Sri Sritharan, S., 2011. Improving Prediction of the Load-Displacement Response of Axially Loaded Friction Piles. *Geo-Frontiers 2011*, ASCE, pp. 36-45.

Thorne, C.R., 1981. Field Measurements of Rates of Bank Erosion and Bank Material Strength. *Erosion and Sediment Transport Measurement*, pp. 503-512.

Tice, J.A. and Sams, C.E., 1974. Experiences with Landslide Instrumentation in the Southeast. Transportation Research Record, No. 482, pp. 18-29. Tofani, V., Dapporto, S., Vannoci, P. and Casagli, N., 2006. Infiltration, Seepage and Slope Instability Mechanisms During the 20-21 November 2000 Rainstorm in Tuscany, Central Italy. *Natural Hazards and Earth System Sciences*, Vol. 6, pp. 1025-1033.

Tofani, V., Bicocchi, G., Rossi, G., Segoni, S., D'Ambrosio, M., Casagli, N. and Catani, F., 2017, Soil Characterization for Shallow Landslides Modeling: A Case Study in the Northern Apennines (Central Italy). *Landslides*, Vol. 14, pp. 755-770.

Verreydt, K., Van Gemert, D., Houtmeyers, J. and Van Waelderen, J., 2014. Redevelopment of Old Sludge Reservoirs. *APCBEE Procedia*, Vol. 10, pp. 177-181.

White, D.J., Pham, T.V. and Hoevelkamp, K.K., 2007. Support Mechanisms of Rammed Aggregate Piers. I: Experimental Results. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, Vol. 133, No. 12, pp. 1503-1511.

Wineland, J.D., 1975. Borehole Shear Device. Proceedings of the Conference on In Situ Measurement of Soil Properties, ASCE, Vol. I, pp. 511-522.

Xiao, S. and Suleiman, M., 2015. Investigation of Thermo-Mechanical Load Transfer (t-z curves) Behavior of Soil-Energy Pile Interface Using Modified Borehole Shear Tests. *Proceedings IFCEEE 2015*, pp. 1658-1667.

Xiao, S., Suleiman, M. and McCartney, J.S., 2014. Shear Behavior of Silty Soil and Soil-Structure Interface Under Thermal Loading. Proceedings of Geo-Congress 2014 ASCE, pp. 4104-4114.

Yang, H., White, D.J, and Schaefer, V.R., 2006. In-Situ Borehole Shear Test and Rock Borehole Shear Test for Slope Investigations. *GeoShanghai 2006 Site and Materials Characterization*, ASCE.

Yang, H., White, D.J, and Schaefer, V.R., 2008. Investigation of a Landslide Using Borehole Shear Test and Ring Shear Test. *Landslides and Engineered Slopes*, pp. 525-529.

Yang, H., Schaefer, V.R. and White, D.J., 2008. Characterization of Clayey Shales Using Borehole Shear Test and Direct Shear Tests: A Comparison. *Geotechnical and Geophysical Site Characterization*, pp.

Yu, Y.T., Zheng, J.G., Liu, Z.H. and Zhang, J.W., 2016. Borehole Shear Tests and its Application to Loess.

Zhao, Y., Wang, X., Zhang, X., Jia, Z., Zeng, X. and Zhang, H., 2012. Rock Borehole Shear Tests in Dam Foundation of Xiangjiaba Hydropower Station. *Journal of Rock Mechanics and Geotechnical Engineering*, Vol. 4, No. 4, pp. 360-366.